TO BE FILLED BY THE INSPECTING OFFICER (JUNIOR ENGINEER)

e of the Officer

SHAINI BABYT

od for which the certificate is issued

2019-20

are of defect if any

Foundation and Basement

Superstructure

Door and Windows

Wood Work Wrought put up

Roof

Flooring

Miscellaneous cracks, etc.

ny major defects noticed which will render the illding unsafe if any manner

Inether the maintenance works have been done roperly

The unauthorised building conth plinth and 1634 39 002

and (9+3) Stoxy in structurally Stable under normal

weather Conditions and this destricted in issued

Stable to the court order

we p(c) 9642/2019 elt

6/2/2020 2 High Lourst

Whether the structure is sound or not for conducting classes.

- 2- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood, etc.
 - Any additional observations is seemed necessary for the certificate may be furnished separately
 with the certificate.

Certified that the school was inspected by me on 4/3/2020 and found to be fit/unfit to conduct classes for the period 20/9-20 for the reasons stated above.

ace Vadanappaly
ate 4/3/2020



Signature

Designation LSGD SECTION

VADANAPPALLY GM

Thrissur-689614